

	Standard - Plug/Rings Dip/Saddle/Height, Check Detection, Mold Number Reading	With Optical Wall Thickness	Standard - Base & Sealing, Surface Inspection, Mold Number Reading	With Base Stress	With Vision Plug	With Vision Dip / Saddle / Height	Standard - Sidewall Stress, & Dimensional
	Veritas iM		Veritas iB				Veritas iC
DEFECTS (Various Parts Of A Container)							
FINISH DEFECTS:							
Bent or Crooked Finish	♦	♦				♦	
Blisters			♦	♦	♦	♦	
Broken Finish			♦	♦	♦	♦	
Bulged Finish	♦	♦					
Checked Finish	♦	♦					
Checks Under Finish	♦	♦					
Chipped Finish	♦	♦	♦	♦	♦	♦	
Corkage Check	♦	♦					
Crizzled Finish	♦	♦					
Dirty or Rough Finish			♦	♦	♦	♦	
Flange			♦	♦	♦	♦	
Knockout			♦	♦	♦	♦	
Lineover			♦	♦	♦	♦	
Neck Ring Seam			♦	♦	♦	♦	
Offset Finish			♦	♦	♦	♦	
Overpress			♦	♦	♦	♦	
Saddle Finish	♦	♦					
Seeds			♦	♦	♦	♦	
Split Finish	♦	♦					
Stones			♦	♦	♦	♦	
Tear or Under Finish Check	♦	♦					
Unfilled or Dip Finish	♦	♦					
NECK DEFECTS:							
Bent Neck					♦	♦	♦
Choked Neck or Bore	♦	♦					
Danny Neck or Neck Tear	♦	♦					
Dirty Neck							♦
Long Neck	♦	♦				♦	♦
Pinched Neck	♦	♦				♦	♦
Stuck Glass Particles							♦
SHOULDER DEFECTS:							
Shoulder Check	♦	♦					
Sunken Shoulders							♦
Thin Shoulder		♦					
BODY DEFECTS:							
Bird Cage (Bird Swing)							♦
Black Spots							♦
Blank and Blow Mold Seam							♦
Blisters							♦
Body Checks	♦	♦					
Body Dimension							♦
Brush Marks							♦
Bulged Sides							♦
Cold Mold							♦
Dirty Ware							♦
Drag Marks							♦
Freaks							♦
Hot or Panel Checks	♦	♦					
Lap Marks or Wrinkles							♦
Letter Checks	♦	♦					
Loading Marks							♦
Oil Marks							♦
Pressure Checks	♦	♦					
Seeds							♦
Shear Marks							♦
Sidewall Stress							♦
Spikes				♦	♦	♦	♦
Stones							♦
Stuck Glass Particles							♦
Sunken Sides							♦
Swab Ware							♦
Thin Ware		♦					♦
Washboard							♦
BASE DEFECTS:							
Baffle Marks			♦	♦	♦	♦	
Base Check	♦	♦					
Base Leaner							♦
Base Spikes			♦	♦	♦	♦	
Base Stress			♦	♦	♦	♦	
Black Spots			♦	♦	♦	♦	
Blisters			♦	♦	♦	♦	
Dirty Ware			♦	♦	♦	♦	
Oil Marks			♦	♦	♦	♦	
Seeds			♦	♦	♦	♦	
Stones			♦	♦	♦	♦	
Stuck Glass Particles or Tramp Glass			♦	♦	♦	♦	
Swab Ware			♦	♦	♦	♦	
Swung Baffle			♦	♦	♦	♦	
OTHER DEFECTS:							
Broken Ware	♦	♦	♦	♦	♦	♦	♦
Horizontal Tear	♦	♦					♦
Out-Of-Shape Ware (Leaner)							♦
Over-Max Height	♦	♦					♦
Under-Min Height	♦	♦					♦
Uneven or Bad Distribution							♦
Vertical Tear	♦	♦					♦

Innovative Inspection Technology

GERMANY, Neuss Telephone +49 (2131) 3595 0 Telefax +49 (2131) 3595 125 • ITALY, Dego (Savona) Telephone +39 (019) 51 66 1 Telefax +39 (019) 51 66 302 • JAPAN, Kawasaki Telephone +81 (44) 222 7371 Telefax +81 (44) 222 4868 • RUSSIA, Moscow Telephone +7 (095) 937 78 95 Telefax +7 (095) 937 78 40 • SINGAPORE Telephone +65 6778 1466 Telefax +65 6778 9433
 SPAIN, Madrid Telephone +34 (91) 883 6816 Telefax +34 (91) 883 2063 • SWEDEN, Örebro Telephone +46 (19) 307 500 Telefax +46 (19) 307 501 • SWEDEN, Sundsvall Telephone +46 (60) 199 100 Telefax +46 (60) 199 261 • UK, Doncaster Telephone +44 (1302) 347 700 Telefax +44 (1302) 327 810 • USA, Elmira, NY Telephone +1 (607) 734 3671 Telefax +1 (607) 734 1245 • USA, Enfield, CT Telephone +1 (860) 814 4010 Telefax +1 (860) 814 4170 • USA, Owensville, MO Telephone +1 (573) 437 2132 Telefax +1 (573) 437 3146 • www.emhartglass.com • info@emhartglass.com